Prepared By: Jeff Skalberg, P.E., Grundy County Engineer, PO Box 127, Grundy Center, Iowa 50638 Phone: 319-824-6912 Fax: 6913

RESOLUTION #12-2026/2027

WHEREAS: The Grundy County Board of Supervisors is empowered under authority of Sections 331.362, 321.255 and 321.285(4), Code of Iowa (2026) to determine, upon the basis of an engineering and traffic investigation, that the speed limit on any secondary road is greater than is reasonable and proper under the conditions existing, and may determine and declare a reasonable and proper speed limit, and

WHEREAS: Such investigation has been requested and completed in accordance with Manual on Uniform Traffic Control Devices, Section 2B.21, and

WHEREAS: The County Engineer, after reviewing the speed investigation results, has made the recommendation to the Board to set the speed limit on secondary road D35 at lesser speeds at several points due to the conditions of the secondary road.

NOW THEREFORE BE IT RESOLVED by the Grundy County Board of Supervisors that the following speed limits be established and appropriate signs erected at the locations described as follows:

(1) Secondary road (a.k.a. D35) from 1120ft due east of the east Holland Corporate Line; thence due west to the east Holland Corporate Line. The speed limit for this area shall be 45 MPH.

(2) Secondary road (a.k.a. D35) from the west Holland Corporate line; thence northwesterly 260ft. The speed limit for this area shall be 30 MPH.

(3) Secondary road (a.k.a. D35) from 260ft northwesterly of the west Holland Corporate line; thence northwesterly and north to a point 700ft south of the East One-quarter Corner of Section 27, T87N, R17W of the 5th P.M. The speed limit for this area shall be 45 MPH.

Passed and Approved this 2nd day of November 2026.

Heidi Nederhoff, Chairperson
Board of Supervisors

ATTEST:

Alan Tscherter, County Auditor