## **RESOLUTION #43-2018/2019**

**WHEREAS:** The Grundy County Board of Supervisors is empowered under authority of Sections 321.236(8), 321.255, 321.471 to 321.473 of the Code of Iowa to impose weight limitations on highway structures under their jurisdiction and in accordance with the National Bridge Inspection Standards.

**NOW THEREFORE BE IT RESOLVED** by the Grundy County Board of Supervisors that vehicle and load limits be established and that signs be erected advising of the permissible maximum weights thereof on the bridges listed as follows due to Special Hauling Vehicles (SHV): SHV = closely spaced multi-axle single unit trucks (4 to 7 axles)

- Bridge located near NW 1/4 Corner, Sec. 26-89-15, Fairfield Township, (#A-16) New Posting Load 26 – 40 - 40 Tons
- Bridge located near N 1/4 Corner, Sec. 05-89-15, Fairfield Township, (#A-21) New Posting Load 26
   40 40 Tons
- Bridge located near NW 1/4 Corner, Sec. 29-89-17, Pleasant Valley Township, (#C-27) New Posting Load – "One Lane Bridge"
- Bridge located near SW 1/4 Corner, Sec. 29-89-17, Pleasant Valley Township, (#C-28) New Posting Load – 27 – 40 - 40
- Bridge located near W 1/4 Corner, Sec. 30-89-17, Pleasant Valley Township, (#C-29) New Posting "One Lane Bridge"
- Bridge located near E 1/4 Corner, Sec. 10-88-18, Shiloh Township, (#E-10) New Posting Load "One Lane Bridge"
- Bridge located near N 1/4 Corner, Sec. 11-88-17, Colfax Township, (#F-08) New Posting Load "One Lane Bridge"
- Bridge located near SW 1/4 Corner, Sec. 02-88-16, Lincoln Township, (#G-02) New Posting Load —
  "One Lane Bridge"
- Bridge located near SW 1/4 Corner, Sec. 08-88-16, Lincoln Township, (#G-04) New Posting Load –
  "One Lane Bridge"
- Bridge located near SW 1/4 Corner, Sec. 21-87-15, Black Hawk Township, (#I-11) New Posting Load
   28 40 40 Tons
- Bridge located near W 1/4 Corner, Sec.35-87-15, Black Hawk Township, (#I-17) New Posting Load 25 – 39 – 40 Tons
- Bridge located near NW Corner, Sec. 21-87-16, Washington Township, (#J-15) New Posting Load 25 – 39 – 40 Tons
- Bridge located near N 1/4 Corner, Sec. 25-86-18, Felix Township, (#M-21) New Posting Load "One Lane Bridge"
- Bridge located near N 1/4 Corner, Sec. 11-86-17, Clay Township, (#N-06) New Posting Load 28 40 40 Tons
- Bridge located near NE Corner, Sec. 12-86-17, Clay Township, (#N-12) New Posting Load "One Lane Bridge"

**BE IT FURTHER RESOLVED** that all resolutions or parts of resolutions in conflict with the provisions of this resolution are hereby repealed.

Passed and Approved this 24<sup>th</sup> day of June, 2019.

Mark Schildroth, Chairperson

**Grundy County Board of Supervisors** 

ha Shillet

Rhonda R. Deters, Grundy County Auditor